

PCN Number:	20190213000.0	PCN Date:	February 18, 2019
Title:	Datasheet for TPS735-Q1		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
Texas Instruments Incorporated is announcing an information only notification. The product datasheet(s) is being updated as summarized below. The following change history provides further details.			
		TPS735-Q1	
<small>SBVS252B –OCTOBER 2014 –REVISED FEBRUARY 2019</small>			
Changes from Revision A (January 2015) to Revision B			Page
• Added title to first page figure			1
• Changed time scale from 10 ms to 10 μ s in <i>TPS73525-Q1 Turn-On Response ($V_{IN} = V_{EN}$)</i> figure			13
• Changed time scale from 10 ms to 10 μ s in <i>TPS73525-Q1 Turn-On Response Using EN</i> figure			13
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
TPS735-Q1	SBVS252A	SBVS252B	
These changes may be reviewed at the datasheet links provided.			
http://www.ti.com/product/TPS735-Q1			
Reason for Change:			
To accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
TPS73501QDRBRQ1	TPS73512QDRBRQ1	TPS73515QDRBRQ1	TPS73518QDRBRQ1
TPS73525QDRBRQ1	TPS73527QDRBRQ1	TPS73530QDRBRQ1	TPS73533QDRBRQ1

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
WW PCN Team	PCN_ww_admin_team@list.ti.com