



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000918I

DATE: 02-Mar-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX7034EVKIT-315#	N/A			Part reactivated from prior notice: M000874I
Lead-Free Conversion	MAX1480BCPI-G10	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5404EUB	MAX5404EUB+	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX699CWE	MAX699CWE+	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Divestiture	MAXREFDES14#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	DG308ADK	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DG411DK	DG411CY+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DG417DK	DG417CY+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DG418DK	DG418CY+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DG421DK	DG421DY+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DG441DK	DG441DY+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DS1077U-100+W	DS1077U-100+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1085LZ-5+W	DS1085LZ-5+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1086LU-455/T+W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1086LU-533+W	DS1086LU-533+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1088LU-02A+W	DS1088LU-02A+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1088LU-737/T+W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1094LU+	DS1094LU-42M+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1094LU+T	DS1094LU-42M+T	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1135U-25+W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1810R-10+T&R-W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1810R-5+T&R-W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1816R-5-U+W	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	DS1833-15+T&R/STR	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DS1833Z-15+T&R	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	DS3992Z-09P+W	DS3992Z-09P+	02-Mar-2017	02-Mar-2017	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Apr-2017

Discontinuance	DS4150P+W	DS4150P+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX1009C/D-C7H	MAX1009C/D-CCG	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1075ETC+	MAX1071ETC+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1075ETC+T	MAX1071ETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1078ETC+	MAX1076ETC+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1078ETC+T	MAX1076ETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1079ETC+	MAX1077ETC+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1079ETC+T	MAX1077ETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1102EUA+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1108EUB+TG07	MAX1108EUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1109CUB+G07	MAX1109CUB+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1109CUB+TG07	MAX1109CUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1225ETC+	MAX1224ETC+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1225ETC+T	MAX1224ETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1279AETC+T	MAX1277AETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1279BETC+T	MAX1277BETC+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX130CMH+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX130CMH+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX130CQH+3-D	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX130CQH+D	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX130CQH+TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131ACQH+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131ACQH+TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131CMH+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131CMH+TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131CQH+TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX131EPL+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1358BETL+TW	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1358BETL+W	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1385BETM+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1385BUTM+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1385BUTM+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX1385EVC16	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX1452EVKIT-NS	MAX1452EVKIT-NS+	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX16101A2910+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16101A2910+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Apr-2017

Discontinuance	MAX16101UK+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16103I4617+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16103I4617+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16103UT+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16107UT+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16109KA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16109O1707MA+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16112KA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16114O16MC+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16114O16MC+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16114Q17MA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16114Q17MA+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16114UT+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16116UT+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16118KA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX16120KA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+D	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+TW	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX2160EBG+W	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX4091AUK+10	MAX4091AUK+T10	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX4232AKA+TC2F	MAX4232AKA+T	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX4268ESD+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX4390EUK+G126	MAX4390EUK+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX44205AUB+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX44260C/D	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX44264LABS#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX44283EVEKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX44291LABS#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX44292ASA+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX4494AKA+G0N	MAX4494AKA+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX498CWI+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5109EEE+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5116EEE+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Apr-2017

Discontinuance	MAX5700AUB+T	MAX5702BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5701AUB+T	MAX5702BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5702AATB+	MAX5702BATB+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5702AAUB+T	MAX5702BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5703AKA+T	MAX5705BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5703ATA+T	MAX5705BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5703AUB+T	MAX5705BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5704AKA+T	MAX5705BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5704ATA+T	MAX5705BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5704AUB+T	MAX5705BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5705AAUB+T	MAX5705BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5713AUD+T	MAX5715BAUD+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5715AAUD+W	MAX5715BAUD+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5723AUP+T	MAX5725BAUP+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5725AAUP+T	MAX5725BAUP+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5801AUB+T	MAX5802BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5802AAUB+T	MAX5802BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5803AKA+T	MAX5805BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5804AKA+T	MAX5805BATB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5804ATA+T	MAX5805BATB+	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5804AUB+T	MAX5805BAUB+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5815AAUD+T	MAX5815BAUD+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5815AUD+T	MAX5815BAUD+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5823AUP+T	MAX5825BAUP+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5824AUP+T	MAX5825BAUP+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX5825AAUP+T	MAX5825BAUP+T	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX6370KA/V+	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX6370KA/V+T	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX7049EVKIT-868#	MAX7037EVKIT#	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX7232CFIQH+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX7232CFIQH+D	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX77178EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX77300EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX77311QEWE+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX77311QEWE+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX77601EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Apr-2017

Discontinuance	MAX77611EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX77660EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX77663WEVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX77871EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX809TEUR+TCEH	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX86000EFD+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX8674EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8678EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8683EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8699EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8877EZK28+GF4	MAX8877EZK28+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX8877EZK28+TGF4	MAX8877EZK28+	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX8907BEVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8909CEVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8923XETI+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX8923XETI+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX8923XETI+TGA8	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX8950EVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8966EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8974AEVKIT#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8987EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8987SEVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8996EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX8998EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX9643EVKIT+	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MAX9660ETA+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX9660ETA+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAX98300SETA+	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAX98300SETA+T	N/A	02-Mar-2017	02-Mar-2017	The part was not released
Discontinuance	MAXQ7670AATL/V+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAXQ7670ATL+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAXQ7670ATL/V+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MAXREFDES149#	N/A	02-Mar-2017	02-Mar-2017	EVKIT is No Longer Supported
Discontinuance	MX7224TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7228K/D	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7228KCWG+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 02-Apr-2017

Discontinuance	MX7228KEWG+	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7228KEWG+T	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7520SD	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7521SD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7521TD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7533TD	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7541ATD	N/A	02-Mar-2017	02-Mar-2017	Part can no longer be manufactured
Discontinuance	MX7542GTD	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7542TD	N/A	02-Mar-2017	02-Mar-2017	Part is leaded. Request information on lead-free version